

Keithley Instruments 28775 Aurora Road Cleveland, Ohio 44139 1-800-935-5595 http://www.tek.com/keithley

Software Release Notes & Installation Instructions

Important information

The 4200A-SCS Clarius⁺ software application suite is a release of the software for the 4200A-SCS. Clarius⁺ software requires **Microsoft**[®] **Windows**[®] **10** to be installed on your 4200A-SCS Parameter Analyzer.

Introduction

This document provides supplemental information regarding the behavior of Clarius⁺ software. This information is grouped into six categories:

Revision history	Lists the version of software, the document version, and the date of the software release.	
New features / enhancements	Summary of each significant new feature included in Clarius software and the 4200A-SCS.	
Problem fixes	Summary of each significant software/firmware bug fix in Clarius+ software and the 4200A-SCS.	
Known problems	Description of each significant known problem and ways to work around it.	
Usage notes	Helpful information describing how to optimize the performance of Clarius ⁺ software and the 4200A-SCS.	
Installation instructions	Detailed instructions describing how to install all software components, firmware, and help files.	

Revision history

This document is periodically updated and distributed with releases and service packs to provide the most up-to-date information. This revision history is included below.

Date	Software version	Document number	Version
5/3/2019	V1.6.1	0771326	08
2/28/2019	V1.6	0771326	07
6/8/2018	V1.5	0771326	06
2/23/2018	V1.4.1	0771326	05
11/30/2017	V1.4	0771326	04
5/8/2017	V1.3	0771326	03
3/24/2017	V1.2	0771326	02
10/31/2016	V1.1	0771326	01
9/1/2016	V1.0	0771326	00

New features/enhancements

Issue number	SCS-4381 / AR 62666
Subsystem	KXCI
Enhancement	The *IDN? and *RST commands have been added to the KXCI command set.

Problem fixes

Issue number	SCS-4353 / AR-62553	
Subsystem	Clarius	
Symptom	SMU does not output 0 A when it is used in Open operation mode of an ITM.	
Resolution	This issue has been corrected.	
Issue number	SCS-4355	
Subsystem	Clarius	
Symptom	After upgrading to Clarius+ V1.6, Clarius was unable to open due to the default project being corrupted. Clarius will show "Could not load xxxxxxx" error, where xxxxxx is the project name.	
Resolution	This issue has been corrected.	
Issue number	SCS-4357	
Subsystem	KULT	
Symptom	While running a demo on the 4200A-SCS, the pmu-1ch-wfm test in the Library outputs an	
Resolution	-831 error when executing this test with the default set parameters. This issue has been corrected.	
Issue number	SCS-4358	
Subsystem	KULT	
Symptom	The current cmake file does not include a path to the LIB environment variable used by Visual Studio.	
Resolution	This issue has been corrected.	
Issue number	SCS-4361	
Subsystem	KULT	
Symptom	User modules in libraries may result in an error due to precision checking. Limit checking on input double point parameters is the main cause.	
Resolution	This issue has been corrected.	
Issue number	SCS-4362	
Subsystem	Clarius	
Symptom Resolution	Using the IRange setting at 10mA in the pram-set and pream-reset tests, an error of -40 occurs. Error message states that the "Current range of the PMU should be set to 1e2 or less to ensure RPMs are used". The 10mA is a valid selection and should not error. This issue has been corrected.	
Nesolution	THIS ISSUE HAS DEEN CONTECTED.	

Issue number	SCS-4364	
Subsystem	Clarius	
Symptom Resolution	In the PMU_SegArb_ExampleFull user module in the PMU_examples_ulib, two of the input parameters of the "Enter Values" GUI of the SegArb Config do not save but revert back to the default values. Both of the modified values in the Waveform Sequence List and the removal of the Seq2 tab do not Save. Once you select Save the values revert to the defaults. This issue has been corrected.	
Issue number	SCS-4370	
Subsystem	Clarius	
Symptom	The flashdisturb-nand and flashendurance-nand projects do not open correctly. This issue also applies to any segment stress project that was updated from Clarius V1.5 to V1.6 or imported from the S4200.	
Resolution	This issue has been corrected.	
Issue number	SCS-4374	
Subsystem	Clarius	
Symptom	A customer's user module using a constant buffer terminated with " \n " caused a memory access violation.	
Resolution	This issue has been corrected.	
Issue number	SCS-4378	
Subsystem	KULT	
Symptom	The vdpulib user library failed to rebuild using rebuildkilibs.bat, resulting in a linker error.	
Resolution	This issue has been corrected.	
Issue number	SCS-4385	
Subsystem	Clarius	
Symptom	In some cases, the reramSweep user module in the nvm user library can limit the SMU current by a value that is less than the specified current compliance when using a fixed current range.	
Resolution	This issue has been corrected.	

Known problems

Issue number	SCS-619	
Subsystem	Clarius	
Symptom	The Configure screen's All Parameter view does not include entries for the PMU's Load Line Effect Compensation and DUT Resistance options.	
Workaround	Select Key Parameters pane on the Configure screen. In the right pane, select Terminal Settings, then select Advanced to open the PMU Advanced Terminal Settings dialog box, where you can enter PMU Load Line Effect Compensation and DUT Resistance values.	
Issue number	SCS-3534	
Subsystem	Clarius	
Symptom	When copying a test from one subsite to another subsite, more rows of data may be copied than exist. The extra rows are copies of the last valid row.	
Workaround	To keep this situation from occurring, set up the subsite and tests completely before collecting data. When creating a new collection of subsite tests copied from existing subsites, run from this new subsite or higher to generate a new, valid set of data.	

Issue number	SCS-3574	
Subsystem	Clarius ⁺ applications, including Clarius, KCon, KXCI, KPulse, Message Console, Firmware Upgrade, and InitializeNewUser	
Symptom	Clarius and the other Clarius ⁺ applications noted above to make required system changes without prompting for increased privileges each time they are launched. It also allows third-party applications including applications potentially categorized as malware, to make system changes without such prompts. You may wish to enable UAC notifications to provide an additional layer of protection when running third-party applications on the 4200A-SCS.	
Workaround		
Issue number	SCS-3959	
Subsystem	System	
Symptom	When installing Clarius ⁺ , if software dependencies are required they will be installed and may require a reboot. When prompted for a reboot, if No is chosen and the install is attempted again without a reboot, the installation will fail.	
Workaround	Uninstall Clarius ⁺ , if necessary, and re-install, allowing reboots when requested.	

Usage notes

4200A-CVIV

Before using the 4200A-CVIV Multi-Switch, be sure to connect the SMUs, using the 4200-PAs and 4200A-CVIV-SPT SMU Pass-Thru modules, and the CVU instrument cables to the 4200A-CVIV inputs. Then run the "Update Preamp, RPM, and CVIV Configuration" option in KCon. Make sure to close the Clarius application before opening KCon on the desktop. Include the action <code>cviv-configure</code> before a SMU or CVU test in the project tree to switch between I-V and C-V measurements.

4225-RPM

Before using the 4225-RPM Remote Amplifier Switch Module to switch between I-V, C-V, and Pulse ITMs, be sure to connect all instrument cables to the RPM inputs, and run the "Update Preamp, RPM, and CVIV Configuration" option in KCon. Make sure to close the Clarius application before opening KCon on the desktop.

When using the 4225-RPM in UTMs, include the call in your user module to the LPT command rpm_config(). The RPM_switch user module in the pmuulib User Library is deprecated. For more information, see the Help pane in Clarius.

4210-CVU

When choosing the Custom Cable Length in the CVU Connection Compensation dialog box of the Tools menu to perform open, short, and load simultaneously, you must run Measure Custom Cable Length first. Then, enable Open, Short, and Load CVU Compensation within a test.

If you are performing Open, Short, and Load CVU Compensation when the CVU is connected to the CVIV, it is recommended that you use the <code>cvu-cviv-comp-collect</code> action.

42x0 SMUs

Under certain conditions, when running SMU current sweeps at very fast ramp rates, the SMU may report compliance unexpectedly. This may occur if the sweep ramps are too high or too fast.

The workarounds for this situation are:

- a. Use the setmode command when generating user modules to turn off the compliance indicator value. With this workaround, the reading will be returned as 105% of the present range.
- b. Use smaller sweep and ramp rates (dv/dt or di/dt).
- c. Use fixed SMU ranges.

Keithley Default User Libraries

The User Libraries in Clarius⁺ software were compiled with Visual Studio C++. If your 4200A-SCS has a different version of Visual Studio installed (see version list below) and you wish to change or debug (using the debug task feature described in Section 8 of the 4200A-SCS Reference Manual) any of the user libraries listed below (see Default User Libraries table), you will need to recompile all modules in that user library. You will then rebuild the user library. If you do not recompile all user modules, you will receive the error "LINK: fatal error LNK1207: incompatible PDB format in <your usrlib>; delete and rebuild." Follow this message or use the provided batch file, reBuildKILibs.bat, for this purpose. reBuildKILibs.bat will compile all modules and build all user libraries listed in the Default User Libraries section below. reBuildKILibs.bat is in C:\S4200\sys\bin. Earlier versions of Visual Studio may install and operate properly but are not supported.

Versions of Visual Studio supported by Clarius+ software:

- Microsoft Visual Studio 2017 C++
- Microsoft Visual Studio 2015 C++
- Microsoft Visual Studio 2013 C++

LPTLIB

- 1. If a voltage limit of greater than 20 V is needed from a SMU set to force zero current, a measv call should be used to set the SMU to auto range to a higher range or set a higher voltage range with rangev.
- 2. If a current limit of greater than 10 mA is needed from a SMU set to force zero volts, a measi call should be used to set the SMU to auto range to a higher range or set a higher current range with rangei.

KULT

If you make changes to or need to rebuild ki82ulib, please note that ki82ulib depends on ki590ulib and winulib. You must specify these dependencies in the Options > Library Dependencies menu in KULT before building ki82ulib. The Options > Build Library function will fail if the dependencies are not properly selected.

KXCI

In KXCI System Mode, in both KI4200A emulation and HP4145 emulation, the following default current measurement ranges exist.

"Limited Auto – 1nA" is the default current measurement range for 4200 SMUs with preamplifiers.

"Limited Auto – 100nA" is the default current measurement range for 4200 SMUs without preamplifiers.

NOTE: If a different bottom range is needed, use the RG command to set the specified channel to a lower bottom range.

Example:

RG 1,1e-11

This will set SMU1 (with preamplifier) to the "Limited Auto - 10pA" range.

Subsite Stress Mode

In "Stress/Measure Mode," the "Leave Stress Conditions On" checkbox will maintain the stress voltage or current during the subsequent device testing. However, if the system configuration includes a matrix, then all outputs will be turned off, regardless of the checkbox, to prevent damaging matrix relays. Likewise, with a 4200A-CVIV Switch in the configuration, all outputs will be turned off if any signals are routed through the 4200A-CVIV Switch, regardless of the checkbox setting. The stress signals can be left on if they are all directly connected outside of the CVIV Switch, but they will be reset when a CVIV connection is made in the subsequent device testing to prevent damaging relays.

Windows® mapped network drive error

When installing Clarius⁺ on a PC, Microsoft[®] policy settings can limit Clarius from accessing mapped network drives in its file windows.

Modifying the registry will fix this issue.

To modify the registry:

- 1. Run regedit.
- 2. Navigate to

HKEY LOCAL MACHINE/SOFTWARE/Microsoft/Windows/CurrentVersion/Policies/System.

- 3. If one does not exist, create a new DWORD entry named EnableLinkedConnections.
- 4. Set the value to 1.
- 5. Restart the PC.

PC Installation, Help Pane PDF Link errors

When installing Clarius⁺ on a PC, PDF links may not open in Clarius from the help pane if you have Acrobat Reader installed and protected mode enabled.

Modifying Internet Explorer settings will fix this issue.

To modify the Internet Explorer settings:

- 1. Open Internet explorer.
- 2. Select Internet Settings.
- 3. On the general tab, find the Startup section, and change "Start with tabs from the last session" to "Start with home page."

PC Installation, language packs

Clarius does not support additional languages in Windows® 10 besides the English (United States) base language. If you encounter errors with Clarius while a language pack is installed, follow Microsoft® instructions for removing the language pack.

Installation instructions

These directions are provided as a reference if you need to re-install Clarius+ software on your 4200A-SCS.

NOTE: All CVU Open, Short, and Load compensation constants must be re-acquired after V1.2 is installed.

STEP 1. Archive your user-modified user library data (optional)

CAUTION: Installing Clarius+ software will reinstall the C:\4200\kiuser\usrlib. If you made changes to the user library and do not want to lose these changes when this software is installed, copy these files to an alternate location before installation.

The easiest way to archive the user library is to copy the entire C:\S4200\kiuser\usrlib folder to a network drive or an archive area on the 4200A-SCS hard drive. Copy the files back after installation to restore them.

STEP 2. Install the 4200A-SCS Clarius+ Software Tools

If you are installing Clarius+ software using the supplied USB drive, follow these instructions:

- 1. Insert the 4200A-SCS Clarius* software USB flash drive into a 4200A-SCS USB port.
- 2. Double-click the **setup.exe** file on the USB drive to install the software on your 4200A-SCS.
- 3. Follow the on-screen installation instructions. If a previous version of Clarius+ software is installed on your 4200A-SCS, you will be asked if you want to remove it. When asked, select OK to continue; selecting No will abort the installation. If a previous version of Clarius+ software is uninstalled, you must restart the system and then install the new Clarius+ software version.
- After the installation is complete, remove the USB flash drive and select Yes, I want to restart
 my computer now to restart the 4200A-SCS before attempting to initialize or use the software
 tools.

If you are downloading and installing the Clarius+ software from www.tek.com, follow these instructions:

- 1. Go to www.tek.com
- 2. Click the **DOWNLOADS** link.
- 3. From the DOWNLOAD TYPE list, choose **Software**.
- 4. For MODEL OR KEYWORD, type 4200A, and click SEARCH.
- 5. Click the software link that you want to download (note that you will need to log in or register to continue).
- 6. Once you are logged in, click the **Download File** button and choose where to download your file (rename the file as needed).
- 7. Unzip the downloaded file.
- 8. Double-click the **setup.exe** file to install the software on your 4200A-SCS.
- 9. Follow the on-screen installation instructions. If a previous version of Clarius+ software is installed on your 4200A-SCS, you will be asked if you want to remove it. When asked, select OK to continue; selecting No will abort the installation. If a previous version of Clarius+ software is uninstalled, you must restart the system and then install the new Clarius+ software version.
- 10. After the installation is complete select **Yes**, **I want to restart my computer now** to restart the 4200A-SCS before attempting to initialize or use the software tools.

077132608 / May 2019 7

STEP 3. Initialize each 4200A-SCS User Account

NOTE: Each user account on the 4200A-SCS must be properly initialized before attempting to run any of the Clarius⁺ software tools. Failure to initialize may cause unpredictable behavior.

From the Windows® login screen, type the user name and password of the account to be initialized. This will need to be done for each of the two default Keithley factory accounts, and for any additional accounts added by the System Administrator. The two factory accounts are:

User name	Password
kiadmin	kiadmin1
kiuser	kiuser1

When Windows® has completed startup, select **Start** > **Keithley Instruments** > **Initialize New User**. This will initialize the user who is currently logged in.


Repeat steps 1 and 2 for both Keithley accounts and for any additional accounts added by the system administrator.

STEP 4. Upgrade 42x0-SMU, 422x-PxU, 4225-RPM, 4225-RPM-LR, 4210-CVU and 4200A-CVIV Firmware

- **NOTE:** Clarius software checks for compatible instrument firmware during startup and will not run if all instruments have not been upgraded to compatible firmware versions.
- NOTE: To find the current hardware and firmware versions of your 4200A-SCS cards, use the KCon utility and select each card.
- **NOTE**: The firmware upgrade program will automatically indicate the hardware that needs upgraded to the approved or latest firmware version.
- NOTE: 4200A-SCS cards are organized by families of related models as shown in the table below. To upgrade the firmware of your 4200A-SCS cards:

CAUTION: It is strongly recommended that you connect the 4200A-SCS to an uninterruptible power supply during the firmware upgrade process. If power is lost during the firmware upgrade, the instruments may no longer be functional and will require factory servicing.

- 1. Exit all Clarius+ software programs and any other Windows® programs.
- 2. From the Windows® taskbar, select Start.
- 3. In the Keithley Instruments folder, select the **Firmware Upgrade** tool.
- 4. If your instrument needs to be upgraded, the Upgrade button becomes visible and there is an indication in Status that an Upgrade is required for a instrument as shown below.
- 5. Select Upgrade.
- 6. The upgrade is not complete, and CVU1 requires upgrading.



The Firmware Upgrade Utility window

Version Table

4200A-SCS instrument family	Hardware version from KCon	Firmware version
4200-SMU/4210-SMU ¹	05,XXXXXXXX or 5,XXXXXXXX	H31
	06,XXXXXXXX or 6,XXXXXXXX	M31
4200-PA	<this be="" cannot="" field="" flash="" in="" product="" the="" upgraded=""></this>	_
4210-CVU	ALL (3.0, 3.1, 4.0 and later)	2.14
4220-PGU/4225-PMU ²	1.0 and later	2.05
4225-RPM/4225-RPM-LR	1.0 and later	2.00
4200A-CVIV ³	1.0	1.04
4200A-TUM	1.0	1.0.0

¹ There are two different models of SMUs available in the 4200A-SCS, 4200-SMU (medium power) and 4210-SMU (high power); both models use the same firmware file.

² The 4225-PMU and 4220-PGU share the same pulse and source board. The 4225-PMU adds measure capability through an additional hardware board but uses the same firmware file.

³ The 4200A-CVIV firmware contains two files to upgrade. The firmware utility will use both files in the version folder.