

## Model 2420 3A SourceMeter®

## Service Manual Addendum

Keithley Instruments, Inc. 28775 Aurora Road Cleveland, Ohio 44139 (440) 248-0400

Fax: (440) 248-6168

This addendum is being provided in order to supply you with the latest information in the least possible time. Please read this information and incorporate it into the manual before using the instrument.

On page 4-12, replace the Battery replacement precautions paragraph with the following information.

## **Battery replacement precautions**

**WARNING** 

There is a danger of explosion if battery is incorrectly replaced. Replace only with the same or equivalent type recommended by the manufacturer. Dispose of used batteries according to manufacturer's instructions.

WARNING

The precautions below must be followed to avoid personal injury.

- Wear safety glasses or goggles when working with lithium batteries.
- Do not short the battery terminals together.
- Keep lithium batteries away from all liquids.
- Do not attempt to recharge lithium batteries.
- Observe proper polarity when inserting the battery in its holder.
- Do not incinerate or otherwise expose the battery to excessive heat (>60°C).
- Bulk quantities of lithium batteries should be disposed of as a hazardous waste.